



CONSUMER NOTICE


STOP PRODUCT USE

DX TYPE REGULATOR FIRST STAGES

Oceanic has been notified by its supplier (ROMI, Ent.) that they have received isolated reports of DX type Regulator First Stages exhibiting uncontrolled flow of air to the Second Stage.

Evaluation has shown that a specific batch of HP (High Pressure) Seats contained material that can deteriorate and fail to properly perform its mechanical sealing (shut off) function, causing an uncontrollable free flow which could result in serious injury to or death of the user.


DX type First Stages affected by this notice include those shipped to Oceanic Retailers from the factory between May 1, 2006, and November 15, 2006. Other model DX type First Stages, such as the CDX, DXi, DX3, DX4, and TDX5, that received annual service between May 1, 2006, and October 22, 2007, may also be affected.

 **NOTE:** Due to the random nature utilized to assign SNs (serial numbers) to First Stages, there is only a small quantity of affected units within the large range of SNs. Since the extent of listing the actual SNs of all affected units would be impractical and not user friendly, Oceanic has created a data base on the OceanicWorldwide web site that product owners and retailers can easily access to determine whether a specific First Stage is affected and if it has received the retrofit.

If you have an affected unit, you must discontinue further use of it and take it to the Oceanic Dealer where you purchased it, or a local Authorized Oceanic Service Center, for a component retrofit at no charge.

Should you have any questions, please contact our toll free Recall Help line at (888) 636-9390 or locally at (510) 639-5448 between 8 am and 5 pm Monday through Friday Pacific Time.

If you no longer own the DX (diaphragm) type Regulator First Stage, please forward this letter to the new owner or have them contact us directly.

 **WARNING:** DO NOT CONTINUE USE of the Regulator First Stage until it receives a Retrofit. Only Authorized Oceanic Dealers and their trained service technicians must perform this Retrofit. Non authorized persons who attempt the Retrofit procedure risk voiding the product's warranty and rendering the product dangerously unsafe for SCUBA use.

Thank you for your cooperation.

Sincerely,

Oceanic