

Recall Notice

SureLock II Weight Pocket Handles

Aqua Lung is conducting a voluntary recall of SureLock II weight pocket handles. SureLock II is the mechanical weight release system found on most Aqua Lung buoyancy compensators (BCs) beginning in 2009. Aqua Lung is concerned about the rubber handle pulling off of the plastic SureLock II weight pocket assembly. If this were to occur during a dive, the weight pocket would be left engaged inside the BC. There are no known occurrences of this happening underwater, and there have not been any reported injuries, but Aqua Lung believes that a recall is the safe and prudent thing to do. Aqua Lung has made a revision to the handle assembly that strengthens it. A revised handle is easily recognized by a thickened band of rubber at the base of the handle.



Remedy: Consumers should immediately stop using their BCs with Sure Lock II weight pockets. Bring the pockets to your nearest authorized Aqua Lung Dive Retailer or Dive Center. They will be able to replace your handles for you while you wait, as changing handles is a quick process. The replacement is made under warranty and you will not incur any charges.

***Please note that handles will be in short supply for the first three weeks.

This recall is being conducted in cooperation with the U.S. Consumer Product Safety Commission

U.S. (except Hawaii) and Caribbean Dealers - for additional assistance please call us at 888-818-3483 or 760-597-5000 or email us at support@aqualung.com.

Hawaii and Micronesia Dealers - for additional information, please call us at 808-485-0100 or email us at pacsupport@aqualung.com.
