

TECHNICAL BULLETIN

Description: Freeflow Control Device (PN AP0233)

Dear Customer,

This bulletin is being issued to pass on information regarding the compatibility of the Miflex hose and the Apeks freeflow control device AP0233. It has come to our attention that the Miflex regulator hose may not be fully compatible with the FCD, due to a variance in manufacturing dimensions of the hose nut. There is an internal chamfer on the 9/16" swivel nut, that when fitted to the FCD comes into direct contact with the collar of the FCD and moves it forward, which in turn slightly restricts the gas flow.

Please make your customers aware of this issue if they wish to purchase and fit the Miflex hose to their regulator or if they wish to purchase an FCD and fit this to a regulator already assembled with a Miflex hose.



**Should you have any questions regarding this,
please contact Aqualung Customer Service at:
(877) 253-DIVE or (760) 597-5000**